

FLOW CHARACTERISTICS OF A R2000 RESTRICTOR FLOWING
 OXYGEN MFC IS EXHAUSTING TO VACUUM




FIG. 3

CHANGING FLOW SENSITIVITY TO PRESSURE CHANGES
 AT DIFFERENT FLOWS




FIG. 4




FIG. 5



3/5

TRANSDUCER STABILITY: DUT ERROR RELATIVE TO A CAPACITANCE DIAPHRAGM GAGE REFERENCE




FIG. 6




FIG. 7A




FIG. 7B

FIG. 7C

HI/LOW MFC: STABILITY TEST AT VARIOUS EXHAUST PRESSURES, 64 HOURS, 6230 CALIBRATION POINTS




FIG. 7D

HI/LOW MFC: STABILITY TEST AT VARIOUS EXHAUST PRESSURES, 64 HOURS, 6230 CALIBRATION POINTS

